

SCHOOL-RELATED CRASH INFRASTRUCTURE REVIEW MONTGOMERY COUNTY DEPARTMENT OF TRANSPORTATION (MCDOT)

• Location: I-270Y Southbound Ramp 8 to Democracy Boulevard

• **Crash Date:** August 27, 2025

Crash Time: Approximately 8:17 AM
School Name: Walter Johnson High School
School Walkshed Boundary: ☑ Inside

Local Case No: 250038291Review Date: October 21, 2025

DESCRIPTION OF INCIDENT AND CRASH DETAIL

On Wednesday, August 27, 2025, a pedestrian was in the crosswalk along the ramp from I-270 Spur Southbound to Democracy Boulevard when the pedestrian stated they darted across the ramp without looking and was struck by a motorist. The crash report indicated the incident occurred within a marked crosswalk. The pedestrian suffered a possible injury and was transported to the hospital. The weather was clear, and the roadway was dry. Figure 2 illustrates the crash location and the direction of pedestrian and vehicle travel.

SCHOOL-SPECIFIC CONTEXT

• School Type: ☑ High

• School Hours (Arrival / Dismissal): 7:45 AM – 2:30 PM

School Enrollment: 2,984 (FY 23-24)
Crossing Guards Present: □ Yes ☑ No

INFRASTRUCTURE & CONDITIONS

• Sidewalk Coverage

There is continuous sidewalk coverage on the north and south side of the road. The facility on the north side is a shared use path.

• Crosswalk Visibility

The diagonal hatched crosswalk markings are in good condition.

• Lighting at Location

The street light closest to the crosswalk was not operational at the arrival time. Other street lights along the ramp were illuminated at the time.

• Speed Limit / School Zone Limit

The speed limit along Democracy Boulevard is 35 mph and the advisory speed limit along the off-ramp is 35 mph. The school zone limit along Democracy Boulevard to the east of the crash location is 35 mph.

• Intersection Geometry

The off-ramp to Democracy Boulevard from I-270Y Southbound is one lane, expanding to three (3) lanes for a distance of approximately 200 feet, with one uncontrolled channelized right-turn lane towards Democracy Boulevard westbound, and two lanes towards Democracy Boulevard eastbound. The crash location occurred along the channelized right turn to Democracy Boulevard westbound. The lane width is approximately 22-feet with a 6-foot left shoulder.

Nearby Transit Stop

There are no bus stops within 1,500 feet of the crash location.

• Nearby School Facilities

The school is located approximately ¾-mile to the east of the crash location.

SITE OBSERVATIONS

• Observation Date/Time: 7:00 AM-7:45 AM, Tuesday, October 21, 2025.

• Pedestrian Activity

Two pedestrians were observed and one bicyclist was observed crossing the ramp.

• Vehicle Activity: ☑ High.

• Drop-off / Pick-up Operations

No drop-off or pick-up patterns observed at the crash location.

• Visibility / Obstructions

A bush is located on the right side of the ramp approaching the crosswalk. Pedestrian sight distance is adequate at the crosswalk ramp.

Driver Behavior

Drivers approach the crosswalk at free flow speeds departing I-270. While there is a separate lane to merge onto Democracy Boulevard, most were observed to slow or stop downstream of the crossing before continuing onto Democracy Boulevard.

Additional Details

A Yield sign exists at the I-270Y SB off-ramp to Democracy Boulevard even though there is a lane addition. Not a heavy pedestrian area as there are no bus stops nearby or large pedestrian generators.

CRASH HISTORY (AT THE LOCATION)

- Total Crashes (Last 5 Years): A total of 13 crashes occurred at or near the subject crash location between January 1, 2020 and October 1, 2025.
 - o **Pedestrian/Bicycle Involved:** Only the subject crash involved a pedestrian.
 - o **Student-Involved Crashes:** Only the subject crash involved a student.
 - o **Crashes During School Hours:** Of the 13 crashes, five (5) crashes occurred within school hours or within one hour of the school bell (6:45 AM to 3:30 PM) and within the school calendar year.
 - o **Recurrent Patterns (Time/Type):** The most prominent crash type included single vehicle crashes, with five (5) collisions. Single vehicle crashes may be due to motorists speeding along the off-ramp and departing the roadway. The remaining crashes include four (4) rear end collisions, three (3) angle collisions, and one (1) rear to side collision.

FINDINGS

There were no obvious infrastructure deficiencies that contributed to this crash. The crash occurred due to driver and failure to exercise due care approaching an uncontrolled pedestrian crossing and pedestrian inattentiveness.

RECOMMENDATIONS

While not related to the crash, the following were identified as recommendations to enhance the safety of the location:



- ☑ **Signage Enhancements:** Upgrade W11-15 signage to meet current retro reflectivity requirements. Post warning sign assemblies on both sides of the uncontrolled crossing. Insall advance warning sign assembly alerting motorists of trail users across the ramp. Replace outdated pedestrian/bicyclist signing with W11-15 sign.
- Maintenance: Replace the existing diagonal hatched crosswalk with continental crosswalk markings over both ramps at the intersection with Democracy Boulevard. Upgrade existing HPS streetlights to LED and ensure all circuits and lights are functioning properly. Trim back vegetation along the I-270Y SB off-ramp towards Democracy Boulevard westbound on the right side of the ramp.

SITE PHOTOS / MAPS

- ☑ Photos Attached
- Z Crash Diagram Included
- ☑ School Walk Zone Map Included









Figure 2 – Crash Diagram






Figure 3 – Crash History (2020-2025)




Figure 4 – School Walk Zone Map