

Germantown Observation Drive Reconstruction (P096604)

Category: Montgomery College
 Sub Category: Higher Education
 Administering Agency: Montgomery College (AAGE15)
 Planning Area: Germantown

Date Last Modified: 11/17/14
 Required Adequate Public Facility: No
 Relocation Impact: None
 Status: Final Design Stage

	Total	Thru FY16	Rem FY16	Total 6 Years	FY 17	FY 18	FY 19	FY 20	FY 21	FY 22	Beyond 6 Yrs
--	-------	-----------	----------	---------------	-------	-------	-------	-------	-------	-------	--------------

EXPENDITURE SCHEDULE (\$000s)

Planning, Design and Supervision	1,000	0	0	1,000	350	500	150	0	0	0	0
Land	0	0	0	0	0	0	0	0	0	0	0
Site Improvements and Utilities	0	0	0	0	0	0	0	0	0	0	0
Construction	0	0	0	0	0	0	0	0	0	0	0
Other	0	0	0	0	0	0	0	0	0	0	0
Total	1,000	0	0	1,000	350	500	150	0	0	0	0

FUNDING SCHEDULE (\$000s)

G.O. Bonds	1,000	0	0	1,000	350	500	150	0	0	0	0
Total	1,000	0	0	1,000	350	500	150	0	0	0	0

APPROPRIATION AND EXPENDITURE DATA (000s)

Appropriation Request	FY 18	0
Supplemental Appropriation Request		0
Transfer		0
Cumulative Appropriation		1,000
Expenditure / Encumbrances		0
Unencumbered Balance		1,000

Date First Appropriation	FY 09	
First Cost Estimate		
Current Scope	FY09	1,000
Last FY's Cost Estimate		1,000

Description

This project funds the design for reconstruction of the existing main entrance road, and for signage at the Observation Drive/MD-118 entrance into the Campus. On-going repairs to the main road on the Germantown Campus are no longer sufficient and existing conditions require a major reconstruction. Originally constructed in the mid 1970's, this road was largely constructed on grade without the sub-base construction that is now typical for roads with the heavy vehicle and bus traffic that the Campus operations impose.

Justification

During the Fall 2014 semester, 7,316 students attended the Germantown campus, and the existing main entrance road (Observation Drive) is inadequate for serving the current and growing student body and requires reconstruction due to the heavy vehicle and bus traffic currently experienced on the campus. According to the Geotechnical Report for Observation Drive Pavement Assessment, problems identified with the existing Observation Drive are the non-existent sub base, longitudinal cracks, alligator cracks, potholes, and raveling. Related studies include the Collegewide Facilities Condition Assessment (12/13), and the Geotechnical Report for Observation Drive Pavement Assessment (5/07).

Other

Funding Source: G.O. Bonds.

Coordination

Site Improvements: College (CIP No. P076601)