M:\Studies\C Locations\Cedar Lane\Fatal Review Jan 2025\90939_Cedar Lane Fatal Review updated.docx

Fatal Crash Review

Location: 9000 block of Cedar Lane near Amherst Lane

Crash Date: Wednesday, January 22, 2025 Crash Time: Approximately 2:40 AM

Local Case Number: 250003002

Review Date: January 24, 2025

Approved: MLP

01/31/2025

Location and Site Description:

The crash location is along southbound Cedar Lane, south of Amherst Lane. Cedar Lane is classified as an area Connector. It is a two-lane closed section roadway with a double yellow centerline and white edge lines on the west side of the roadway. The posted speed limit along Cedar Lane 30 mph.

Description of Crash:

Based on the police crash report, a vehicle (unit 1) traveling southbound on Cedar Lane, south of Amherst Lane, when for unknown reasons, it went on to the shoulder and collided with an unoccupied parked vehicle (unit 2), which overturned onto its roof and struck an unoccupied parked vehicle (unit 3). The driver of unit 1 suffered life-threatening injuries.

Observations:

A field investigation was conducted on Friday, January 24, 2025, at 11:30 AM. The crash location is on Cedar Lane approximately 125 feet south of Amherst Lane. The double yellow centerline and white edge line pavement markings are in good condition. All marked crosswalks, and the pedestrian refuge islands are in good condition. Speed limit signs (30 mph) are present within 100 feet of the crash location on both approaches are visible and in good condition. The alignment for Cedar Lane is straight with a slight over-vertical along the roadway on both approaches to the crash site.

Recommendations

None

Site Pictures



Southbound Cedar Lane, approaching crash location



Northbound Cedar Lane, approaching crash location`



crash location



crash location

M:\Studies\C Locations\Cedar Lane\Fatal Review Jan 2025\90939_Cedar Lane Fatal Review updated.docx



crash location