

X

MONTGOMERY COUNTY **EXECUTIVE ORDER**

Offices of the County Executive • 101 Monroe Street • Rockville, Maryland 20850

Subject Fire Lane Establishment Order for 8401 Turkey Thicket Drive	Executive Order No. 131-13	Subject Suffix	
Originating Department Montgomery County Fire and Rescue Service	Department Number MCFRS 22-13	Effective Date 7/16/2013	


Fire Lane Establishment Order

Pursuant to Section 22 - 33, Montgomery County Code, 1971, as amended, you are hereby e hereby ordered to no elow. When signs po e the enforcement an order must be of ac

ost fire lane sign ad paint work (p Tthis Fire Lane l	e Lane has been established as described in this order. You are as and paint curbs/pavement (painting optional) as identified be eainting optional) have been completed, this order will authorize by appropriate police and fire officials. Compliance with this of days of receipt.
LOCATION:	Montgomery County Multi-Agency Service Park
-	8401 Turkey Thicket Dr.
	as where indicated by signs and paint. e attached diagram for location of sign placement) Signs must be posted so that it is not possible to park a vehicle without being
FIRE LAN	in sight of a sign. Signs may be no further
(Red letters or	white background)
<u>PAINT</u> (Se	e attached diagram if painting).
	Paint must be traffic yellow with lines of

sufficient width to be readily identifiable/ readable by motor vehicle operators.

Fire Chief, Montgomery County Fire and Rescue Service



P.301.948.2750 F.301.948.9067

www.solteszco.com

MONTGOMERY COUNTY, MARYLAND


1"= 50'

1989-00-00

0.1198900001_Phase 2 DFNIENGINEERIPAVSTORMFire Access/FireSignage_1_8.5X11.sht Scale=50.0000 ft / in. User=metters PLTdv=PDF_Grey_300.pitctg Pentbl=TEXT_SUB.tbi 6/25/2013 8:11:46 AM

2 OF 5


06/05/2013



LEGEND

NOTE:

- 1. ALL FIRE ACCESS ROUTES MUST BE DESIGNED TO SUPPORT 85,000 lbs.
- 2. FIRE DEPARTMENT ACCESS ROADWAYS LESS THAN 28' MUST HAVE NO PARKING SIGNS SPACED AT NO MORE THAN 100' APART ON BOTH SIDES OF ACCESS ROAD.



PROPOSED FIRE HYDRANT LOCATION



PROPOSED NO PARKING/FIRE LANE SIGNS



SOLTESZ

2 Research Place, Suite 100 Rockville, MD 20850 P.301.948.2750 F.301.948.9067 www.solteszco.com FIRE ORDER SIGNAGE PLAN

PSTA & MONTGOMERY COUNTY MULLTI AGENCY SERVICE PARK

GAITERSBURG (9TH) ELECTION DISTRICT MONTGOMERY COUNTY, MARYLAND

3 OF 5


6/25/2013 8:13:05 AM

QX19890000_Phase 2 DFN/ENGINEER/PAVSTORM/Fire Access/FireSignage_2_8.5X11.sht Scale=50.0000 ft / in. User=metters PLTdrv=PDF_Grey_300.pltcfg Pentbl=TEXT_SUB.tbl

1989-00-00

1"= 50"

06/05/2013



1989-00-00

1"= 50'


4 OF

06/05/2013

The original of this drawing document was prepared by Soltesz, Inc. (Soltesz). If this document was not obtained directly from Soltesz and/or it was transmitted electronically, Soltesz cannot guarantee that unauthorized changes and / or alterations were not made by others. If verification of the information contained hereon is needed, contact should be made directly with Soltesz. Soltesz makes no warranties, express or implied, concerning the accuracy of any information that has been transmitted by electronic means.

www.solteszco.com







SOLTESZ

2 Research Place, Suite 100 Rockville, MD 20850 P.301.948.2750 F.301.948.9067 www.solteszco.com

PSTA & MONTGOMERY COUNTY MULLTI AGENCY SERVICE PARK

GAITERSBURG (9TH) ELECTION DISTRICT MONTGOMERY COUNTY, MARYLAND

5 OF

1989-00-00

1"= 50'

06/05/2013