


## Dedicated but Unmaintained County Roads (DBUCR) Program CIP No. 501117

## Ardwick Drive, Waycroft Way and Golf Lane Improvement



January 2014

Montgomery County Department of Transportation Division of Transportation Engineering

100 Edison Park Drive, Fourth Floor Gaithersburg, Maryland 20878

. •

## TABLE OF CONTENTS

I.	INTROI	DUCTION	2	
II.	BACKG	ROUND		
	1. Back	ground of DBUCR Policy	2	
	2. Back	ground of DBUCR Roads and Public Information	2	
III.	EXISTI	NG CONDITION		
	1. Road	dway	3	
		fic and Road Characteristics	5	
	3. Drai		. 5	
		ties and Streetlights	8	
	5. Tree	es s	8	
IV.	CONCE	EPTUAL DESIGN		
	1. Roa	dway	8	
		mwater Management & Drainage	9	
		ities and Streetlights	10	
٠	4. Tree		11	
V.	PROJE	CT SCHEDULE	11	
VI.	PROJE	CT COST ESTIMATE	11	
APPEN	DICES			
Appendi	х А	List of DBUCR Roads		
Appendi		Application submitted by the Wickford Community	Association	
Appendi	х С	Aerial GIS Map with Soil and Drainage Boundaries	D	
Appendi	хD	Stormwater Management Concept for Closed Section	n Design	
Appendi	хE	Proposed Typical Section		
Appendi	x F	Standard No. MC-301.03		
		Residential Driveway Open Section Road		
Appendi		List of Affected Properties	on Design	
Appendi	хH	Itemized Construction Cost Estimate for Open Section 1. Cost Estimate for Closed Sec	on Design	
Appendi	хI	Itemized Construction Cost Estimate for Closed Sec	ngament Cost	
Appendi	x J	Design, Property Acquisition and Construction Man Estimate	agement Cost	

#### I. INTRODUCTION

Montgomery County Department of Transportation (MCDOT), Division of Transportation Engineering prepared this report for Wickford Community Association which is comprised of the residents on Ardwick Drive, Waycroft Way and Golf Lane in Rockville for the DBUCR program. A majority of the residents in Wickford Community signed a petition requesting their roads to be evaluated as a part of the DBUCR program.

This report describes an overview of the DBUCR program, the existing conditions of the three roads, conceptual design, project schedule, and a budgetary cost estimate for the project.

#### II. BACKGROUND

## 1. Background of DBUCR Policy

The following is a chronological order for the establishment of the DBUCR policy:

- The County Council appropriated funds in Fiscal Year (FY) 2008 Capital Budget for developing the DBUCR policy.
- July 2007-June 2008 (FY 2008)-Community stakeholders and representative from the County met periodically and developed the policy.
- September, 2009-the County Executive transmitted a draft policy to the County Council.
- October, 2009 County Council Transportation and Environment (T&E) Committee reviewed and commented on the draft policy.
- December, 2009-the DBUCR Policy was adopted.
- January, 2010-The County Executive recommended the Capital Improvement Program (CIP) budget for the DBUCR program.
- May, 2010-The County Council approved CIP for DBUCR.

### 2. Background of DBUCR Roads and Public Information

MCDOT compiled the list of DBUCR roads from a report by Montgomery County Civic Federation and the County's inventory utilizing the latest State Highway Administration (SHA) MAARS Report, Geographic Information System (GIS) map/aerial photos, existing subdivision plats, existing deeds, and status of the County maintenance by the County's depots. As a result of the research, a total of fifty nine roads within the County have been identified as the DBUCR roads. The list is included in Appendix A.

As required by the DBUCR policy, two public information meetings were held for the property owners who reside adjacent to the identified DBUCR roads. The two public information meetings were held to provide every affected property owner an opportunity to attend one of the public information meetings to understand the program better and address any of their concerns regarding the program. The meetings were held on September 22, 2010 and October 12, 2010.

The DBUCR program divides into the following four categories:

- 1. Self Build/Self Maintain
- 2. Self Build/County Maintain
- 3. County Build/County Maintain
- 4. No Build (Do Nothing)

MCDOT received an application from Wickford Community Association on September 26, 2012. The application is included in Appendix B.


The plats related to the Wickford community original subdivision are dated from 1948 to 1959.

### III. EXISTING CONDITION

MCDOT developed a plan sheet from an aerial photo for Ardwick Drive, Waycroft Way and Golf Lane to assist in the existing conditions assessment. MCDOT also conducted a site visit to Wickford Community on November 21, 2013.

### 1. Roadway


Ardwick Drive is approximately 1,150 feet long with its width varying from 16 feet to 19.5 feet. Waycoft Way is approximately 1,400 feet long with its varying width from 16 feet to 24 feet. Golf Lane is approximately 850 feet long with its varying width from 16 feet to 19 feet. All three roads were paved by WSSC in spring, 2012. The roads are open section. Some locations have grass ditches on both sides, and some locations do not have any ditches. The roads have a slight crown in the middle.



Ardwick Drive



Waycroft Way



Golf Lane

## 2. Traffic and Road Characteristics

The roads are Tertiary Residential Streets with no cut-through traffic from near-by arterial roads. Typical numbers of residential vehicle trips are generated from the neighborhoods. Access from Golf Lane across North Bethesda Trail is currently prohibited. There are also no existing sidewalks along the roads.

### 3. Drainage

The drainage areas are delineated in aerial GIS map in Appendix C. There four main drainage areas within the project site. The runoff from the four drainage areas drains into the outfall riprap at the south side of Golf Lane near the entrance of Ardwick Drive and Waycroft Way. The rip-rap extends further out into the Georgetown Preparatory School campus. The drainage areas are composed of Glenelg Silt Loam and Urban Land as shown on the aerial map.

Some stormwater flows into the existing grass ditches along the road. However, some parts of the community do not have grass ditches along the road. The runoff along Waycroft Way flows into the existing curb-inlet at north of the intersection of Waycroft Way and Wickford Drive. There is a culvert at the downstream in each of Drainage Areas No. 2-4. The stormwater from the three culverts flows into a box with a grate on top in the median of

Ardwick Drive and Waycroft Way. Then the stormwater flows out into the outfall to the existing rip-rap in the Georgetown Preparatory campus.



Upstream of Culvert at the Intersection of Ardwick Drive and Waycroft Way



Downstream of Ardwick Drive and Waycroft Way



Culvert at the Downstream of Golf Lane



Rip-Rap from Downstream of Golf Lane into the Georgetown Preparatory Campus

### 4. Utilities and Streetlights

MCDOT investigated existing utilities within the project site.

There are water and sewer facilities provided by WSSC. In spring 2012, WSSC replaced water mains and repaved the roads after their replacement work. There are also facilities by Washington Gas Company in the community. There are PEPCO utility poles within the project site.

There are currently no street lights along the roads.

#### 5. Trees

There is a wide range of size of trees in the community. Some of them are 24" and greater in the diameter of trunk. Some of those major trees may be impacted by the construction of the proposed flat bottom grass ditch along the both sides of the road.

#### IV. CONCEPTUAL DESIGN

### 1. Roadway

The proposed typical section for Ardwick Drive, Waycroft way and Golf Lane Improvement is shown in Appendix E.

MCDOT standard width for a Tertiary Residential Street is 20 feet. In retrofit situations, MCDOT accepts 18 feet wide roadway with a 20 feet minimum clearance. The 20 feet minimum clearance is required for adequate access for emergency vehicles. For the roadway widening, MCDOT proposes to increase the width to 18 feet at minimum with at least of one foot of clearance on both sides of the road for emergency vehicles access.

MCDOT took pavement core samples from Ardwick Drive, Waycroft Way and Golf Lane on December 2, 2013. The pavement core sample locations are shown on the map in Appendix C. Based on the core samples, Golf Lane has adequate pavement thickness. The thickness of existing pavement is only 4.75" on Ardwick Drive and is 4.5" on Waycroft Way. The County proposes 1.5" of overlay surface in bituminous concrete for Ardwick Drive and Waycroft Way. For the proposed roadway widening portions on Ardwick Drive, Waycroft Way and Golf Lane, the County proposes 6" of bituminous concrete. MCDOT standard for pavement thickness is 6" for Tertiary Residential Street.

The existing storm drain pipe with 15" diameter Corrugated Metal Pipe (CMP) from the northwest corner of the intersection of Ardwick Drive and Golf Lane to the junction box in the median and another existing storm drain pipe with 15" diameter CMP from the northeast corner of the intersection of Waycroft Way and Golf Lane to the same junction box will be replaced with 15" Reinforced Concrete Pipes (RCP). The existing storm pipe from intersection of Ardwick Drive and Waycroft Way to the junction box will be replaced with 21" RCP.

There are a total number of forty four driveways that are adjacent to the roads. Each of the forty four driveways will have a new culvert pipe be installed under it based on the County's Standard No. MC-301.03. The standard is included in Appendix F.

## **Closed Section Design**

For the closed section design, a combination of curb inlets and yard inlets are proposed. The storm drain schematic for the closed section design is included in Appendix D. The locations of curb inlets, yard inlets and manholes are noted in the schematic drawing. A combination of High Density Polyethylene (HDPE) pipe and RCP in the range of 15" to 30" of diameter are proposed.

## 3. Utilities and Streetlights

Based on the field observations, MCDOT estimated that two PEPCO poles within the project site would have to be relocated. One location is between House No 1113 and 1117 on Waycroft Way and the other location is southeast corner of Wickford Drive and Waycroft Way. The cost was added to the construction cost estimate. During the design phase, prior rights will be investigated by the County's Property Acquisition Section to determine whether the County or PEPCO would be responsible for the relocation cost. MCDOT will be coordinate with PEPCO to determine any need for the relocation of the utility poles. Two existing fire hydrants will have to be relocated and the top of existing sewer manhole will to be reset as a result of the paving. The County's construction contractor will perform any relocation work on the facilities by WSSC. One gas valve by Washington Gas will have to be vertically adjusted as well. Any relocations of the Washington Gas Company facilities are done by the gas company prior to starting of the construction.

Streetlights can be added to the scope of the project upon the community's request.



**Pavement Core Samples** 

Core Number	Core Location	Core Thickness	Subgrade Type
1	5409 Golf Lane	9.5" Total 4.25" HMA Multiple Layers *5.25" bottom layer raveled apart	Soil
2	11108 Waycroft Way	4.5" HMA Surface Layer	Aggregate
3	11028 Ardwick Drive	4.75" HMA Surface Layer	Aggregate
4	5509 Golf Lane	10"+ Total 6.5" HMA Multiple Layers *3.5"+ bottom layer raveled apart	Unknown

## 2. Stormwater Management & Drainage

MCDOT provides the Warwick Community a choice between an open-section road with two feet wide flat bottom swales for drainage and a closed-section road with curb and gutter along the both sides of the roads. The following are stormwater management and drainage concept for each design.

### **Open Section Design**

The existing yard inlet at the northeast corner of the intersection of Waycroft Way and Golf Lane will be replaced with a new yard inlet that meets MCDOT standard. The junction box in the median of Ardwick Drive and Waycroft Way will also be replaced with a yard inlet that meets MCDOT standard.

#### 4. Trees

Trees will be impacted by the roadway project. The number of trees impacted will be defined as more information is obtained in the engineering design phase. During the design phase, impacts to trees will be studied. MCDOT will replace an equal number of the trees that will be removed as a part of the project. However, the County cannot guarantee that the same species of trees will be planted in place of removed trees. The landscaping cost has been added to the construction cost estimate.

#### V. PROJECT SCHEDULE

The following is a **tentative schedule** based upon the assumption that the County Executive and the County Council will approve the funding for Ardwick Drive, Waycroft Way and Golf Lane in the upcoming CIP budget request for FY17-23. The County's fiscal year starts in July 1. The County's FY 17 starts on July 1, 2016.

Phase	Duration	Starting Date	Ending Date
Design	12 months	July, 2016	June, 2017
Property Acquisition	9 months	July, 2017	March, 2018
Construction	3 months	April, 2018	June, 2018

MCDOT included the property acquisition phase in case easements are needed for road reconstruction. The minimum duration for the property acquisition phase is nine months.

## VI. PROJECT COST ESTIMATE

A total project cost has been estimated for budgetary basis. The total project cost is \$451,000 for the open section design and \$733,000 for the closed section design. As shown in Appendix F, there are a total number of forty five affected properties. The total project cost will be equally divided among the forty five properties. Each household will be responsible for paying the County approximately \$9,000 for the open section design and \$15,000 for the closed section after deduction of the County's participation cost which is 10% of the total project cost.

### **Open Section Design**

<u>County's Participation Cost</u> \$451,000 X 0.1 = \$45,100

Individual Affected Property Household Cost (\$451,000-\$45,100)/45 = \$9,020 (Say \$9,000)

## **Closed Section Design**

<u>County's Participation Cost</u> \$733,000 X 0.1 = \$73,300

<u>Individual Affected Property Household Cost</u> (\$733,000-\$73,300)/45 = \$14,660 (Say \$15,000)

Each project cost includes design, property acquisition and construction cost. The design cost includes a geotechnical report, permit fees for stormwater management concept and erosion and sediment control, a topographic and boundary survey, and engineering design cost. See appendices I through J for cost breakdown.

**Open Section Design** 

Design	\$43,000
Construction Management	\$77,000
Land	\$6,000
Construction Materials &	
Labor	\$325,000
Total Project Cost	\$451,000

**Closed Section Design** 

<u> </u>	
Design	\$43,000
Construction Management	\$77,000
Land	\$6,000
Construction Materials &	
Labor	\$607,000
Total Project Cost	\$733,000

# APPENDIX A

List of DBU Roads

Updated : September 22, 2010

	Ending Point Total					
No.	Road Name Starting Point (Mil		(Miles)	(Miles)	Town	
	7,000 1,000	0.22 (North of Riding	(11111111111111111111111111111111111111			
1 1	AITCHESON LA	Stable Road)	0.70	0.48	LAUREL	
2	ANCHORAGE DR	MACARTHUR BLVD	0.13	0.13	BETHESDA	
			ANCHORAGE			
3	ANCHORAGE PL.	BOLLING LA	DR/.08	0.08	BETHESDA	
	, ,	0.1 (Northwest of	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
4	ANDERSON ST.	Octagon Lane)	0.18	80.0	SILVER SPRING	
	V W W		WAYCROFT			
5	ARDWICK DR	GOLF LA.	WAY/.22	0.22	ROCKVILLE	
6	ATTLEBORO RD	NORWOOD RD	DUXBURY DR/0.25	0.25	SILVER SPRING	
		0.09 (South of				
7	AUTH LA	Hermleigh Road)	0.13	0.04	SILVER SPRING	
8	BELFAST RL	KINGSGATE RD	0.15	0.15	POTOMAC	
9	BELLE COTE DR	KRUHM RD	0.42	0.42	BURTONSVILLE	
		0.36 (North of Olney				
10	BENTLEY RD	Sandy Spring Road)	0.50	0.14	OLNEY	
11	BIRCHCREST LA	FREDERICK RD	0.22	0.22	CLARKSBURG	
12	BISHOP DR	WINTHROP DR	0.05	0.05	SILVER SPRING	
13	BLANTON RD	GOOD HOPE RD	0.15	0.15	SILVER SPRING	
<u> </u>		3332	ANCHORAGE			
14	BOLLING LA	ANCHORAGE DR	PL./0.11	0.11	BETHESDA	
15	BRATTON DR	SUNSET DR	BRATTON CT/0.09	0.09	ROCKVILLE	
16	BROOKS RD	RIDGE DR	KIRK LA/0.15	0.15	ROCKVILLE	
17	CARNAGIE AVE	NEEDWOOD RD	0.12	0.12	DERWOOD	
18	CINDY LA	SEVEN LOCKS RD	0.08	0.08	BETHESDA	
		3-1-1-0-1-1-1		****		
19	CIRCLE DR RIDGE DR/0.68		GLEN MILL RD/1.02	0.34	ROCKVILLE	
		ONTOLL DIV				
20	CLOVER LA PERSIMMON TREE RD		0.06	0.06	POTOMAC	
		0.22 (South of Briggs				
21	CREST HILL LA	Chaney Road)	0.51	0.29	SILVER SPRING	
22	CROWFOOT LA	COPLEY LA	0,09	0.09	SILVER SPRING	
		0.2 (North of Olney				
23	DOMINION DR	Sandy Spring Road)	0.25	0.05	SANDY SPRING	
24	DUXBURY RD	ATTLEBORO RD	0,14	0.14	SILVER SPRING	
25	ECKMOOR RD	ELDRID DR	0.05	0.05	SILVER SPRING	
26	EMORY ST	MUNCASTER MILL RD	0.07	0.07	GAITHERSBURG	
		GLENALLAN AVE	WALLAÇE			
27	ERSKINE AVE		AVE/0.10	0.10	SILVER SPRING	
28	FAWSETT RD	MAÇARTHUR BLVD	0.29	0.29	POTOMAC	
29	GARDNER PL	CHAPELGATE RD	0.11	0.11	GERMANTOWN	
30	GARRETT RD	REDLAND RD/0.00	0.21	0.21	DERWOOD	
	<del>-</del>	0.31 (North of River		<del></del> -		
31	GARY RD	Road)	0.35	0.04	POTOMAC	
		,			,	
32	GOLF LA	MIDDLESHIRE PL/0.10	0.28	0.18	ROCKVILLE	
33	HAW LA	EDNOR RD	0.21	0.21	SILVER SPRING	
34	HAWHILL END	WILDEN LAV.07	0.13	0.06	POTOMAC	

ġE.	HEIL RD	NEW HAMPSHIRE AVE	0.15	0.15	SILVER SPRING
35	HILLER WAY	ROCKVILLE PIKE	0.10	0.10	ROCKVILLE
36	HILLSDALE DR	HILLSDALE DR/.06	0.10	0.04	KENSINGTON
37	KINGSGATE RD	ROCK RUN DR	0.15	0.15	POTOMAC
38 39	KIRK LA	BROOK RD	0.04	0.04	OLNEY
39	LONG BRANCH	BROOKIE			
40	. PKWY	DEARBORN AVE	0.06	0.06	SILVER SPRING
41	MAPLE RIDGE CT	HOLLY RIDGE ROAD	0.15	0.15	ROCKVILLE
42	MERRICK RD	WILSON LA	0.13	0.13	BETHESDA
43	MOULTRIE PKWY	LOGAN DR	0.06	0,06	POTOMAC
43	MOOLINEFRAN	0.38 (South of Ednor			
44	OLD ORCHARD RD	Road)	0.52	0.14	SILVER SPRING
44	OLD OKOLIAIND IND	BREADY RD			
45	OLNEY LA	DKE BI KS	0.26	0.26	OLNEY
46	OVERHILL RD	GARRETT RD	0.21	0.21	DERWOOD
47	PEMBROKE RD	BRADLEY RD	0.14	0.14	BETHESDA
	PEMBIONETA	0.12 (South of Bradley			
48	POE RD	Blvd)	0.16	0.04	BETHESDA
49	POPLAR HILL ROAD		0.70	0.70	GERMANTOWN
50	SILVERWOOD LA	MARYLAND AVE	0.21	0.21	BETHESDA
51	STONE RD	KIRK LA	0.09	0.09	OLNEY
52	SUNCREST AVE	FREDERICK RD	0.18	0.18	CLARKSBURG
53	UNITY LA	GLEN MILL RD	0.31	0.31	POTOMAC
54	UPLAND DR	GOOD HOPE RD	0.17	0.17	SILVER SPRING
55	WAYCROFT WAY	GOLF LA	0.27	0.27	ROCKVILLE
56	WILLOW LA	PINETREE ROAD	0.25	0.25	ROCKVILLE
<del>- 50</del> -	AAIFFOAAFA	1 774-13-2-1-1-1			
57	WINDSWEPT LA	NEW HAMPSHIRE AVE	0.67	0.67	BRINKLOW
58	WINNPENNY LA	CAPE MAY RD	0.07	0.07	SILVER SPRING
59	WINTHROP DR	PIPING ROCK DR	BISHOP RD	0.06	SILVER SPRING
00	TAINTING DIC				

•

# APPENDIX B

Application Submitted by Wickford Community Association

Director, Department of Transportation . Montgomery County, Maryland

Dear Sir:

The community of Wickford, located in Montgomery County in postal code 20852, is requesting that the Department of Transportation perform a preliminary engineering study of our roads under the provisions of the Dedicated But Un-maintained (DBU) program. There are 43 homes that would be impacted by the program. Enclosed are petitions signed by 31 property owners which represent more than the 60% of the impacted properties needed to request the study. All but one of the property owners who we were able to contact during our canvassing efforts signed the petition. Please note that the introductory text for the petition incorrectly states that there are 44 impacted properties. One of properties (11018 Waycroft Way) is counted in that 44 total. However, the property is completely on a County maintained road.

Wickford has maintained its own roads since the community was established in the early 1950's and maintains a road fund for purposes of maintaining the roads. Currently the community has a rather charming rural, village like ambience. There are no street lights or sidewalks, and residents walk the streets and their dogs in what is essentially a big cul-de sac, where many folks stop and chat with their neighbors. Maintaining our own streets does impose a financial burden on the community and issues regarding funding for the roads are often topics for lively discussion at our annual Wickford Community Association meeting. The potential for County maintenance has been discussed frequently over the years. At one time there was the perception and concern that County assumption of maintenance would mean sacrificing green lawns, shrubbery and tress for sidewalks, gutters and such to meet County standards. Our understanding is that now, under current policies, the County assuming maintenance would not necessarily drastically change the rural character of the community. In any case, we realize that only the preliminary engineering study can answer that question. This spring the WSSC repaved almost all of our roads as a result of installing new water pipes throughout the community. Because of this action by WSSC, the roads are in much better shape than they have been in years. We believe that the costs for County improvements may be less than it would otherwise have been and that now is an appropriate time to request the study.

We understand that there is no cost to the community for the study. However, we also understand that if 60% of the impacted property owners approve the proposed project, that the affected property owners would be responsible to pay 90% of the total project cost.

Please let me know if you would like any additional information regarding this request. My contact information is David L. Comis, 11005 Waycroft Way, Rockville, MD 20852 240-669-8315 (h).

Sincerely,

David L. Comes

David L. Comis,

President, Wickford Community Association

Attachments:

Petition for Road Study for Wickford Community (8)

RECEIVED

SEP 26 2012

DIVISION OF TRANSPORTATION ENGINEERING

We the undersigned do hereby request that Montgomery County Department of Transportation perform a study to determine the cost and viability of making improvements to and assuming maintenance for those roads in the Wickford Community that are not currently maintained by the County in accordance with the County's Dedicated But Unmaintained (DBU) County Roads Policy.

Specifically this includes #11008/#11015 to #11116/11113 Ardwick Drive; #5401 to #5509 Golf Lane; and #11000/#11005 to #11112/#11117 Waycroft Way, as well as two properties on Wickford Drive (#5425 and #5430) that border both Waycroft Way and Wickford Drive for a total of 44 Affected Property Owners.

- 1. The study will result in an estimate of project costs. There is no cost to the community for the study.
- 2. Sixty percent of the Affected Property Owners have to request the study.
- 3. The results of the study, when complete, will be reviewed with the community.
- 4. The community will have another opportunity to determine whether or not to proceed based on the project cost. Sixty percent of the Affected Property Owners have to approve going forward with the project.
- 5. If the Community decides to proceed, the project will compete for funding with other projects in the County's bi-enniel CIP budget
- 6. If the project is funded and the project is built, the Affected Property owners will be obligated to reimburse the County's expenses, less the County's contribution, as explained in the County's Dedicated but Unmaintained County Roads Policy.

do explained in a	=		Baka.
Name (Printed)	Address	Signature	Date
1. NANCY WELSS_	5405 GOLFLA	ONE Prency Cloriss	7/10/12
V2. ANN MARKE BOLG	and 55019011	Ten auliterlan	7/10/12
3. LOU BOLAND	11011 WAY CA	Y way Brulls	7/10/12
VA. DANJEL GOLDEN	5430 WICKFOR	odr. 100 A	7-10-12
V5. DAVID L. COMIS	11005 WAYER		1 7-10-12
TO DESCRIPTION OF THE PARTY AND THE PARTY AN	544-605		1/3/11/
16.7. Dien DEEGAN	= 5413 GOLA	LANG MADDRAG	1709/12
		LFLANE/ROSPIGNOZ COL	1 7/18/12
9	445	TEATTER	•
<del>18</del> .	FEDD WAY	1 30 1 10 10	· = 1/5/5/12
V8. DAVID SAUte	n 5409 Gol		2 494/2010
10 200157	ale 11112 1	ferwelde. No. J.	7.6.12
V 9, Politica & Volume	(Anf	26)	

We the undersigned do hereby request that Montgomery County Department of Transportation perform a study to determine the cost and viability of making improvements to and assuming maintenance for those roads in the Wickford Community that are not currently maintained by the County in accordance with the County's Dedicated But Unmaintained (DBU) County Roads Policy.

Specifically this includes #11008/#11015 to #11116/11113 Ardwick Drive; #5401 to #5509 Golf Lane; and #11000/#11005 to #11112/#11117 Waycroft Way, as well as two properties on Wickford Drive (#5425 and #5430) that border both Waycroft Way and Wickford Drive for a total of 44 Affected Property Owners.

- 1. The study will result in an estimate of project costs. There is no cost to the community for the study.
- 2. Sixty percent of the Affected Property Owners have to request the study.
- 3. The results of the study, when complete, will be reviewed with the community.
- 4. The community will have another opportunity to determine whether or not to proceed based on the project cost. Sixty percent of the Affected Property Owners have to approve going forward with the project.
- 5. If the Community decides to proceed, the project will compete for funding with other projects in the County's bi-enniel CIP budget
- 6. If the project is funded and the project is built, the Affected Property owners will be obligated to reimburse the County's expenses, less the County's contribution, as explained in the County's Dedicated but Unmaintained County Roads Policy.

explaine	d in the County's Dedicated but o	Illianitanica county issues	, Dete
Name (Printe		Signature	Date // >
1. Pappert	4 \	Dr \	-1/19/2
2.1.13.1500	11021 Ardunck	Dr Johnstoll	son 1/11/12
ny 3. Kuhnsm	an 11027 Ardwick	Dried	- Other She
4. Reed	11031 Ardunck	Dr XCurl MRE	2/11/2
5. Patters	on 11101 Ardwick	- Dr Ofly Hall	W /////X
√ 6. \ evi	11105 Ardivick	D- HMUrom W	Levà 7/13/2012
17. White	1409 Ardvick		
	aro) 11113 Arduid	CDV_	,
9. XX dix Kiles			
10.			

We the undersigned do hereby request that Montgomery County Department of Transportation perform a study to determine the cost and viability of making improvements to and assuming maintenance for those roads in the Wickford Community that are not currently maintained by the County in accordance with the County's Dedicated But Unmaintained (DBU) County Roads Policy.

Specifically this includes #11008/#11015 to #11116/11113 Ardwick Drive; #5401 to #5509 Golf Lane; and #11000/#11005 to #11112/#11117 Waycroft Way, as well as two properties on Wickford Drive (#5425 and #5430) that border both Waycroft Way and Wickford Drive for a total of 44 Affected Property Owners.

- 1. The study will result in an estimate of project costs. There is no cost to the community for the study.
- 2. Sixty percent of the Affected Property Owners have to request the study.
- 3. The results of the study, when complete, will be reviewed with the community.
- 4. The community will have another opportunity to determine whether or not to proceed based on the project cost. Sixty percent of the Affected Property Owners have to approve going forward with the project.
- 5. If the Community decides to proceed, the project will compete for funding with other projects in the County's bi-enniel CIP budget
- 6. If the project is funded and the project is built, the Affected Property owners will be obligated to reimburse the County's expenses, less the County's contribution, as explained in the County's Dedicated but Unmaintained County Roads Policy.

			•	,
, p. 6	Kulinsman July	Signature Cottage En	Address 1027 audiwell	Name (Printed)
in rour	Kuknoman Mily	Dindy L	avine Kuhosman Dr.	1. Jonalds Catho
				2.
		•		3.
				4.
				5.
				6.
			OCCUPACION STREET	7.
				8.
				9.
			The second secon	10.

## Petition for Novel Study for Affective Community

We the undersigned do hereby request that Montgomery County Department of Transportation perform a study to determine the cost and viability of making improvements to and assuming maintenance for those roads in the Wickford Community that are not currently maintained by the County in accordance with the County's Dedicated But Unmaintained (DBU) County Roads Policy.

Specifically this includes #11008/#11015 to #11116/11113 Ardwick Drive; #5401 to #5509 Golf Lane; and #11000/#11005 to #11112/#11117 Waycroft Way, as well as two properties on Wickford Drive (#5425 and #5430) that border both Waycroft Way and Wickford Drive for a total of 44 Affected Property Owners.

- The study will result in an estimate of project costs. There is no cost to the community for the study.
- 2. Sixty percent of the Affected Property Owners have to request the study.
- 3. The results of the study, when complete, will be reviewed with the community.
- 4. The community will have another opportunity to determine whether or not to proceed based on the project cost. Sixty percent of the Affected Property Owners have to approve going forward with the project.
  - 5. If the Community decides to proceed, the project will compete for funding with other projects in the County's bi-enniel CIP budget
- If the project is funded and the project is built, the Affected Property owners will be
  obligated to reimburse the County's expenses, less the County's contribution, as
  explained in the County's Dedicated but Unmaintained County Roads Policy.

		8 .1.1	Signature	<b>Date</b>
	Name (Printed)	Address	agreeare M	de a state
	1. GEORGIA B.PERDU	E 11000 U	PALLOGE SHIMM	lesser 117/12
Ĵ	2. Christine Cheson		Waycroft Way Christme	Chay 7/9/12
V	3. BARBARA WALSH	11100 1	NAYCROFT WAY B.A.	mountade Walsh 7/9/12
تسمرا	James Hansel	11112	Waycroft Woy	JOUIN 7/1/12,
· "	5. MARY EMAGUIRE	11012 h	aycroffliby 8 hos	XD/hap 9 1/9/12
Var.	6. Joseph P. Co	(lips. Sn 1	TOE WAYEROFT WAY	Steel Jew 1/10/2
•	er de la companya de	·		
======================================	9.			STATE OF THE STATE
<del>.</del>	10.	And the second s		

We the undersigned do hereby request that Montgomery County Department of Transportation perform a study to determine the cost and viability of making improvements to and assuming maintenance for those roads in the Wickford Community that are not currently maintained by the County in accordance with the County's Dedicated But Unmaintained (DBU) County Roads Policy.

Specifically this includes #11008/#11015 to #11116/11113 Ardwick Drive; #5401 to #5509 Golf Lane; and #11000/#11005 to #11112/#11117 Waycroft Way, as well as two properties on Wickford Drive (#5425 and #5430) that border both Waycroft Way and Wickford Drive for a total of 44 Affected Property Owners.

- 1. The study will result in an estimate of project costs. There is no cost to the community for the study.
- 2. Sixty percent of the Affected Property Owners have to request the study.
- 3. The results of the study, when complete, will be reviewed with the community.
- 4. The community will have another opportunity to determine whether or not to proceed based on the project cost. Sixty percent of the Affected Property Owners have to approve going forward with the project.
- 5. If the Community decides to proceed, the project will compete for funding with other projects in the County's bi-enniel CIP budget
- 6. If the project is funded and the project is built, the Affected Property owners will be obligated to reimburse the County's expenses, less the County's contribution, as explained in the County's Dedicated but Unmaintained County Roads Policy.

- Explained in the	sourity of a contract		
Name (Printed)	Address	Signature	Date 7 -/5-/1
1. Quille	1116 Ardin	ck GUV COM	0 150
V2. (1.11)	1110 ARdw	ict Mel	1-15-12
3. CA-D S-1	11108 ARda	/ Y h a a l . / 3	ney 7.15.12
4. ZINO ONE	III of ALDIA	- // 1	b. 25.12
5. / 4 i X	11100 ARds		7-15-12
6. ACCH	11028 Ardi	/ /	
V7. 520201	11622 Ardia	01 -	7-18-12
8. Lussa/FAMI		wick Fig.	7:25-12
V9. N/SA/	11008 ATT	luick ( See Ather sh	i.t
10.	Jan B		
	76.4		

We the undersigned do hereby request that Montgomery County Department of Transportation perform a study to determine the cost and viability of making improvements to and assuming maintenance for those roads in the Wickford Community that are not currently maintained by the County in accordance with the County's Dedicated But Unmaintained (DBU) County Roads Policy.

Specifically this includes #11008/#11015 to #11116/11113 Ardwick Drive; #5401 to #5509 Golf Lane; and #11000/#11005 to #11112/#11117 Waycroft Way, as well as two properties on Wickford Drive (#5425 and #5430) that border both Waycroft Way and Wickford Drive for a total of 44 Affected Property Owners.

- 1. The study will result in an estimate of project costs. There is no cost to the community for the study.
- 2. Sixty percent of the Affected Property Owners have to request the study.
- 3. The results of the study, when complete, will be reviewed with the community.
- 4. The community will have another opportunity to determine whether or not to proceed based on the project cost. Sixty percent of the Affected Property Owners have to approve going forward with the project.
- 5. If the Community decides to proceed, the project will compete for funding with other projects in the County's bi-enniel CIP budget
- If the project is funded and the project is built, the Affected Property owners will be obligated to reimburse the County's expenses, less the County's contribution, as explained in the County's Dedicated but Unmaintained County Roads Policy.

explained in thi	e County 3 Dedicated Da.	• • • • • • • • • • • • • • • • • • • •		,	Date
Name (Printed)	Address		Signarure	. / _	Date
1. CLAUDIA NO	EAL 11008 ARD	wick de	Gaudi	adjeal	9-13-12
2.	Address  EAL //008 ARD				
3.		<u></u>			
4.					,
5.				<u> </u>	
6.					<del></del>
7.	•				
8.				<del></del>	
9.				<u> </u>	
10.					
				•	

We the undersigned do hereby request that Montgomery County Department of Transportation perform a study to determine the cost and viability of making improvements to and assuming maintenance for those roads in the Wickford Community that are not currently maintained by the County in accordance with the County's Dedicated But Unmaintained (DBU) County Roads Policy.

Specifically this includes #11008/#11015 to #11116/11113 Ardwick Drive; #5401 to #5509 Golf Lane; and #11000/#11005 to #11112/#11117 Waycroft Way, as well as two properties on Wickford Drive (#5425 and #5430) that border both Waycroft Way and Wickford Drive for a total of 44 Affected Property Owners.

- 1. The study will result in an estimate of project costs. There is no cost to the community for the study.
- 2. Sixty percent of the Affected Property Owners have to request the study.
- 3. The results of the study, when complete, will be reviewed with the community.
- 4. The community will have another opportunity to determine whether or not to proceed based on the project cost. Sixty percent of the Affected Property Owners have to approve going forward with the project.
- If the Community decides to proceed, the project will compete for funding with other projects in the County's bi-enniel CIP budget
- 6. If the project is funded and the project is built, the Affected Property owners will be obligated to reimburse the County's expenses, less the County's contribution, as explained in the County's Dedicated but Unmaintained County Roads Policy.

A	lame (Printed)	Addr	ess	Sigr	ature	Date
1.	DENNIS	LASSIA	11101 WAY	20FT WAN	7	9-18-12
2.		7		(	)	
3.						
4.						
5.		•				
6.						
7.	<u> </u>	·				
8.						
9.		,				
10.		CONTRACTOR	· · · · · · · · · · · · · · · · · · ·			
1000	C - Dat Cont + Falcing at 1 age		THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED I	The state of the s		

We the undersigned do hereby request that Montgomery County Department of Transportation perform a study to determine the cost and viability of making improvements to and assuming maintenance for those roads in the Wickford Community that are not currently maintained by the County in accordance with the County's Dedicated But Unmaintained (DBU) County Roads Policy.

Specifically this includes #11008/#11015 to #11116/11113 Ardwick Drive; #5401 to #5509 Golf Lane; and #11000/#11005 to #11112/#11117 Waycroft Way, as well as two properties on Wickford Drive (#5425 and #5430) that border both Waycroft Way and Wickford Drive for a total of 44 Affected Property Owners.

- 1. The study will result in an estimate of project costs. There is no cost to the community for the study.
- 2. Sixty percent of the Affected Property Owners have to request the study.
- 3. The results of the study, when complete, will be reviewed with the community.
- 4. The community will have another opportunity to determine whether or not to proceed based on the project cost. Sixty percent of the Affected Property Owners have to approve going forward with the project.
- 5. If the Community decides to proceed, the project will compete for funding with other projects in the County's bi-enniel CIP budget
- 6. If the project is funded and the project is built, the Affected Property owners will be obligated to reimburse the County's expenses, less the County's contribution, as explained in the County's Dedicated but Unmaintained County Roads Policy.

f	Jame (Printed)	Address		Signature	) v E	Date,
1.	Boh - Clousia	Langara Sterl	WOKOWO	DR KRI	bull _	- 8/10/1
2.	4	Linehan 542	5		700	1 1
3.			·		V	
4.					. •	
5.	1 1					· ·
6.						
7.						
8.						
9.						
10.						

# **APPENDIX C**

Aerial GIS Map with Soil and Drainage Boundaries

DBU-ARDWICK DR, GOLF LN & WAYCROFT WAY

SCALE: NOT TO SCALE JANUARY 2014

# APPENDIX D


Stormwater Management Concept for Closed Section Design



DBU-ARDWICK DR, GOLF LN & WAYCROFT WAY

# APPENDIX E

**Proposed Typical Section** 



TYPICAL SECTION


ARDWICK DRIVE, WAYCROFT WAY AND GOLF LANE IMPROVEMENT

NOTE HMA: HOT MIX ASPHALT

JANUARY 2014 SCALE 1"=5"

## APPENDIX F

Standard No. MC-301.03
Residential Driveway Open Section Road



R/W VARIES

PINDITSTD/MC30103 6-24-94 9:34:23 am

OF ENG. SERVICES

# APPENDIX G

**List of Affected Properties** 

## **List of Affected Property Properties**

Address	Owner's Name
11015 ARDWICK DR	PAPPERT WILLIAM T & S
11021 ARDWICK DR	WILSON JOHN J & M J
11027 ARDWICK DR	KUHNSMAN DONALD L ET AL TR
11031 ARDWICK DR	REED RICHARD N JR TRUSTEE
11101 ARDWICK DR	PATTERSON CHRISTOPHER ET AL
11105 ARDWICK DR	LEVI AMIRAM W & JOSEPHINE
11109 ARDWICK DR	WHITE JEAN C
11113 ARDWICK DR	GEORGETOWN PREPARATORY SCHOOL INC
11116 ARDWICK DR	WILL MARY KATHERINE REILLY TR
11112 ARDWICK DR	WILL WILLIAM K & MARY K REILLY-WILL
11108 ARDWICK DR	CAREY MICHAEL B & CHRSITINE F
11104 ARDWICK DR	ZINGONE GERALD & L A
11100 ARDWICK DR	LAUX JOHN C & MARY L
11028 ARDWICK DR	ASEFF JOHN N & J C
11022 ARDWICK DR	SZCZUR JOHN J & D M
11016 ARDWICK DR	LUSSO PAOLO ET AL
11112 WAYCROFT WAY	HANSELL ANDREA GOODMAN
11108 WAYCROFT WAY	COLLINS JOSEPH P JR & DENISE J
11104 WAYCROFT WAY	LEVI AMIRAM W & JOSEPHINE
11100 WAYCROFT WAY	WALSH THOMAS E JR & B B
11030 WAYCROFT WAY	STENTZ JON W
11028 WAYCROFT WAY	CHESON BRUCE D & C M
11024 WAYCROFT WAY	MAYO WILLIAM M & MARILYN D
11018 WAYCROFT WAY	MUTH ROY W 2ND & V B
11012 WAYCROFT WAY	MAGUIRE MARY F TRUSTEE
11000 WAYCROFT WAY	PERDUE ROBERT E JR & G P
11121 WAYCROFT WAY	SULLIVAN PAUL D & B B
11117 WAYCROFT WAY	SULLIVAN PAUL D & B B
11113 WAYCROFT WAY	KHALILI HOMAYOON & FAYYAZI ELHAM
11109 WAYCROFT WAY	CASSIDY ANDREW G & S B
11105 WAYCROFT WAY	FEGAN JAMES G ET AL TR
11101 WAYCROFT WAY	CASSIDY DENNIS M & M C
11029 WAYCROFT WAY	TROIANO TONI E TR
11027 WAYCROFT WAY	FRAZIER ROBERT T & K C
5425 WICKFORD DR	LINEHAN, ROBERT & CLAUDIA M MEER
5430 WICKFORD DR	GOLDEN DANIEL P ET AL TR
11011 WAYCROFT WAY	BOLAND LOUIS J JR
11005 WAYCROFT WAY	COMIS LEORA E TRUSTEE
##= ##	

5509 GOLF LN	GEORGETOWN PREP SCHOOL INC
5501 GOLF LN	BOLAND JOHN L & ANN M
5413 GOLF LN	DEEGAN RICHARD F ET AL TR
	CORPORATION OF THE ROMAN CATHOLIC
5409 GOLF LN	CLERGYMEN
5405 GOLF LN	WEISS DANIEL L & N C
5401 GOLF LN	ANDERS ALLEN KENT TR ET AL

**Total Number of Affected Properties:** 45

# APPENDIX H

Itemized Construction Cost Estimate for Open Section Design

C. I. P. WORK ORDER CONTRACT PRICING

A	rdwick Drive, Waycroft Way & Golf Lane - EE per Work C				
No.	DESCRIPTION	QUANT.	UNIT	UNIT PRICE	AMOUNT
1001	CLEARING	42	СН	\$150.00	\$6,300.00
1002	UNCLASSIFIED GRUBBING EXCAVATION	4,003	CY	\$5.00	\$20,015.00
1007	ARROW PANELS	40	UD	\$1.00	\$40.00
1008	TEMPORARY TRAFFIC SIGNS	144	SF	\$12.00	\$1,728.00
1023	FLAGGER	320	HR	\$20.00	\$6,400.00
1032	CRUSHER RUN AGGREGATE CR-6 FOR MAINTENANCE OF TRAFFIC	300	TONS	\$4.00	\$1,200.00
1034	CONSTRUCTION STAKEOUT	40	CH	\$80.00	\$3,200.00
2001	UNCLASSIFIED ROADWAY EXCAVATION	302	CY	\$20.00	\$6,040.00
3006	CLASS IV OR CLASS V 15 INCH REINFORCED CONCRETE PIPE	68	LF	\$12.48	\$848.64
3008	CLASS IV OR CLASS V 21 INCH REINFORCED CONCRETE PIPE	116	LF	\$21.58	\$2,503.28
3036	21 INCH X 15 INCH CORRUGATED METAL PIPE ARCH, 16 GAUGE	1,276	LF	\$17.86	\$22,789.36
3046	"J" INLET MCDOT STANDARD No. MC-506.01	8	VF	\$265.60	\$2,124.80
3053	M.S.H.A. CONCRETE MIX No. 2, MIX No. 3, MIX No. 6, SOLID MASONRY AND/OR PRECAST CONCRETE FOR MISCELLANEOUS STRUCTURES	3	СУ	\$440.00	\$1,320.00
3060	M.S.H.A. STANDARD No. MD-368.01 END SECTION FOR 21 INCH REINFORCED CONCRETE PIPE	1	EA	\$434.60	\$434.60
3095	SILT FENCE	6,780	LF	\$1.00	\$6,780.00
3096	REMOVE AND RESET SILT FENCE	6,780	LF	\$1.00	\$6,780.00
3098	STABILIZED CONSTRUCTION ENTRANCE	19	TONS	\$10.00	\$190.00
3099	REHABILITATE STABILIZED CONSTRUCTION ENTRANCE	19	TONS	\$1.00	. \$19.00
4004	SUBFOUNDATION CONCRETE USING M.S.H.A. CONCRETE MIX No. 1	81	CY	\$95.00	\$7,695.00
5003	HOT MIX ASPHALT BASE PAVEMENT FOR ROADWAYS: SUPERPAVE 25.0 MM, PG 64-22	41	TONS	\$70.00	\$2,870.00
5004	HOT MIX ASPHALT SURFACE PAVEMENT FOR ROADWAYS: SUPERPAVE 12.5 MM, PG 64-22	311	TONS	\$75.00	\$23,325.00
6002	COMBINATION CONCRETE CURB & GUTTER (ANY TYPE)	67	LF	\$25.00	\$1,675.00
6007	7 INCH DEPTH PLAIN CONCRETE FOR DRIVEWAYS AND DRIVEWAY APRONS	7,098	SF	\$3.25	\$23,068.50
6033	REMOVE AND RESET/RELOCATE EXISTING FENCE (ANY SIZE, ANY TYPE)	212	SF	\$6.75	\$1,431.00
6042	STONE, BRICK, OR SOLID MASONRY FOR THE RELOCATION OF EXISTING SIGNS, MAILBOXES, DECORATIVE DRIVEWAY ENTRANCE WALLS, TREE WELLS, ETC.	12	SF	\$50.00	\$600.00
6043	REMOVE & RESET/RELOCATE EXISTING MAIL BOX (ANY SIZE, ANY TYPE)	42	EA	\$25.00	\$1,050.00
7014	SODDING	6,038	SY	\$4.00	\$24,152.00
7017	SELECTIVE TREE TRIMMING: 6¼ INCHES IN CALIPER OR LARGER	32	СН	\$150.00	\$4,800.00
7018	SELECTIVE TREE FELLING AND REMOVAL: 61/4 INCHES IN CALIPER OR LARGER	40	СН	\$550.00	\$22,000.00
7019	ADDITIONAL WATERING OF SOD, PLANTS, AND SEEDED AREAS	12	1000 GAL.	\$10.00	\$120.00
7020	TREE ROOT PRUNING	5,447	LF	\$1.00	\$5,447.00

C. I. P. WORK ORDER CONTRACT PRICING

1	C. I. P. WORK ORDER CONTRAC	31 1 100	110		
8003	RELOCATE EXISTING GROUND MOUNTED SIGN USING NEW SUPPORTS	8	SF	\$12.00	\$96.00
8009	ADJUST EXISTING MANHOLES (ANY SIZE, ANY TYPE) TO FINISHED GRADE: DOWN 6 INCHES OR UP 12 INCHES	1	EA	\$330.00	\$330.00
8013	ADJUST EXISTING WASHINGTON GAS VALVE BOX TO FINISHED GRADE (ANY SIZE, ANY TYPE)	1	EA	\$100.00	\$100.00
8015	RELOCATION OF EXISTING FIRE HYDRANT	3	EA	\$200.00	\$600.00
	Subtotal				\$208,072.18
	30% Contingency	].			\$62,421.65
	Non WO Contract Items (PEPCO& Streetlights)	]			\$49,600.00
	Landscaping Cost	<u> </u>			\$ 5,000.00
	Total	]			\$325,093.83
					\$325,000.00

S:\PROJECTS\Projects\501117-DBU\Ardwick Road\[131202 Ardwick-EE.xlsx]current WO Contract

# APPENDIX I

Itemized Construction Cost Estimate for Closed Section Design

C. I. P. WORK ORDER CONTRACT PRICING

A	C. I. P. WORK ORDER CONTRAC rdwick Drive, Waycroft Way & Golf Lane - EE per Work O				
	DESCRIPTION	QUANT.	UNIT	UNIT PRICE	AMOUNT
1001	CLEARING	42	СН	\$150.00	\$6,300.00
	UNCLASSIFIED GRUBBING EXCAVATION	4,003	CY	\$5.00	\$20,015.00
	ARROW PANELS	40	UD	\$1.00	\$40.00
	TEMPORARY TRAFFIC SIGNS	144	SF	\$12.00	\$1,728.00
	FLAGGER	320	HR	\$20.00	\$6,400.00
1023	CRUSHER RUN AGGREGATE CR-6 FOR MAINTENANCE OF TRAFFIC	300	TONS	\$4.00	\$1,200.00
1034	CONSTRUCTION STAKEOUT	40	CH	\$80.00	\$3,200.00
2001	UNCLASSIFIED ROADWAY EXCAVATION	302	CY	\$20.00	\$6,040.00
	CLASS 3 EXCAVTION FOR STORM DRAIN AND MISCELLANEOUS CONSTRUCTION: TOTAL DEPTH OF EXCAVATION LESS THAN OR EQUAL TO 4 VERTICAL FEET	806	CY	\$60.00	\$48,360.00
3006	CLASS IV OR CLASS V 15 INCH REINFORCED CONCRETE PIPE	144	LF '	\$12.48	\$1,797.12
3008	CLASS IV OR CLASS V 21 INCH REINFORCED CONCRETE PIPE	97	LF	\$21.58	\$2,093.26
3011	CLASS IV OR CLASS V 30 INCH REINFORCED CONCRETE PIPE	38	LF	\$40.40	\$1,535.20
3023	15 INCH TYPE S, HIGH DENSITY POLYETHYLENE PIPE	661	LF	\$6.76	\$4,468.36
3023	18 INCH TYPE S, HIGH DENSITY POLYETHYLENE PIPE	348	LF	\$9.24	\$3,215.52
3046	"J" INLET MCDOT STANDARD No. MC-506.01	16	VF	\$265.60	\$4,249.60
3047	"J" INLET AS TERMINUS MCDOT STANDARD No. MC-506.02	12	VF	\$254.40	\$3,052.80
3047	TYPE "B" MANHOLE MCDOT STANDARD No. MC-515.01: FOR THE PORTION OF VERTICAL DEPTH UP TO AND INCLUDING 6 FEET	12	VF	\$200.00	\$2,400.00
3052	TYPE "B" MANHOLE MCDOT STANDARD No. MC-515.01: FOR THE PORTION OF VERTICAL DEPTH GREATER THAN 6 FEET AND LESS THAN OR EQUAL TO 8 FEET	18	VF	\$200.00	\$3,600.00
3053	M.S.H.A. CONCRETE MIX No. 2, MIX No. 3, MIX No. 6, SOLID MASONRY AND/OR PRECAST CONCRETE FOR MISCELLANEOUS STRUCTURES	8	CY	\$440.00	\$3,520.00
2054	STORM DRAIN INLETS THROATS (ANY SIZE, ANY TYPE)	25	LF	\$20.00	\$500.00
3055	TOP SLABS, INCLUDING MANHOLE FRAME AND COVER, FOR STORM DRAIN INLETS (ANY SIZE, ANY TYPE)	2	CY	\$100.00	\$200.00
3060	M.S.H.A. STANDARD No. MD-368.01 END SECTION FOR 21 INCH REINFORCED CONCRETE PIPE	1	EA	\$434.60	\$434.60
3095	SILT FENCE	6,780	LF	\$1.00	\$6,780.00
	REMOVE AND RESET SILT FENCE	6,780	LF	\$1.00	\$6,780.00
	STABILIZED CONSTRUCTION ENTRANCE	19	TONS	\$10.00	\$190.00
3098	REHABILITATE STABILIZED CONSTRUCTION ENTRANCE	19	TONS	\$1.00	\$19.00
4004	SUBFOUNDATION CONCRETE USING M.S.H.A. CONCRETE MIX No. 1	81	CY	\$95.00	\$7,695.00
5003	HOT MIX ASPHALT BASE PAVEMENT FOR ROADWAYS: SUPERPAVE 25.0 MM, PG 64-22	41	TONS	\$70.00	\$2,870.00
5004	HOT MIX ASPHALT SURFACE PAVEMENT FOR ROADWAYS: SUPERPAVE 12.5 MM, PG 64-22	3,11	TONS	\$75.00	
6002	CANY TYPE (ANY TYPE)	6,780	LF	\$25.00	\$169,500.00
6002	7 INCH DEPTH PLAIN CONCRETE FOR DRIVEWAYS AND DRIVEWAY APRONS	7,098	SF	\$3.25	\$23,068.50

C. I. P. WORK ORDER CONTRACT PRICING

	071111				_
6033	REMOVE AND RESET/RELOCATE EXISTING FENCE (ANY SIZE, ANY TYPE)	212	SF	\$6.75	\$1,431.00
6042	STONE, BRICK, OR SOLID MASONRY FOR THE RELOCATION OF EXISTING SIGNS, MAILBOXES, DECORATIVE DRIVEWAY ENTRANCE WALLS, TREE WELLS, ETC.	12	SF	\$50.00	\$600.00
6043	REMOVE & RESET/RELOCATE EXISTING MAIL BOX (ANY SIZE, ANY TYPE)	42	EA	\$25.00	\$1,050.00
7014	SODDING	6,038	SY	\$4.00	\$24,152.00
7017	SELECTIVE TREE TRIMMING: 6¼ INCHES IN CALIPER OR LARGER	32	СН	\$150.00	\$4,800.00
7018	SELECTIVE TREE FELLING AND REMOVAL: 61/4 INCHES IN CALIPER OR LARGER	40	СН	\$550.00	\$22,000.00
7019	ADDITIONAL WATERING OF SOD, PLANTS, AND SEEDED AREAS	12	1000 GAL.	\$10.00	\$120.00
	TREE ROOT PRUNING	5,447	LF	\$1.00	\$5,447.00
8003	RELOCATE EXISTING GROUND MOUNTED SIGN USING NEW SUPPORTS	8	SF	\$12.00	\$96.00
8009	ADJUST EXISTING MANHOLES (ANY SIZE, ANY TYPE) TO FINISHED GRADE: DOWN 6 INCHES OR UP 12 INCHES	. 1	EA	\$330.00	\$330.00
8013	ADJUST EXISTING WASHINGTON GAS VALVE BOX TO FINISHED GRADE (ANY SIZE, ANY TYPE)	1	EA	\$100.00	\$100.00
8015	RELOCATION OF EXISTING FIRE HYDRANT	3	EA	\$200.00	\$600.00
<u> </u>	Subtotal				\$425,302.96
	30% Contingency			ļ	\$127,590.89
	Non WO Contract Items (PEPCO& Streetlights)				\$49,600.00
	Landscaping Cost	1			\$ 5,000.00
	Total	]			\$607,493.85

S:\PROJECTS\Projects\501117-DBU\Ardwick Road\[140109 Ardwick-Closed Section-EE.xlsx]current WO Contract

**Closed Section** 

# APPENDIX J

Design, Property Acquisition and Construction Management Cost Estimate

Project Name: Ardwick Drive, Waycroft Way & Golf Lane

Duration: 12	
(12)	
Design	

			FY17		Total	Rounded
		Duration	Duration   Hours per			
	Hourly Rate		Month	Cost		
Transportation Design	100	. 12	22	26,400		
			•			
Contracts Costs (4 Soil Borings)				10,000		-
Permit Fees (SWM Concept)				2,684		
Permit Fees (E&S)				3,710		
Total Cost				\$42,794	\$42,794 \$ 42,794	43,000

Duration: 6 months = 3 months prior to construction + 3 months construction duration Construction Mgt (13)

			FY18			FY18		Total	Rounded
		Duration	Hours per		Duration	Hours per			
	Hourly Rate	(month)	Month	Cost	(month)	Month	Cost		
Construction Section	100	3	25	7,500	3	200	000'09		٠
Transportation Design	100	3	20	6,000	3	10	3,000	•	
Total Cost				\$13,500			\$63,000	\$ 76,500	77,000

Property (14) Duration: 9 months

			FY18		і отаі	lotal Kounded
		Duration	Hours per			
	Hourly Rate (month)	(month)	Month	Cost		
Property Acquisition Section	100	6	5.5	5.5 4,950		
Temporary Construction						
Easement				800		•
Total Cost				\$ 2,750	\$ 5,750	00009