

Tree Protection - new sidewalk **7.29.22**
Old Baltimore Rd **Rick Holley**
***All root pruning shall be done to a maximum depth of 6"**
DBH = diameter (in.) at breast height (4.5 ft above ground)
Location: F = front, S = side, R = rear, I = island, M = Median, O = Opposite, P = Private, ms = multi-stem
Pruning: s/w = sidewalk, elev = elevation pruning, DW = dead wood removal, d/w = driveway
cli - clear light, csi = clear sign, cpt = clear private tree, clh = clear house, rd = road
Tree Protection: F = fencing required, n/a = no action

Note: refer to *Tree Protection Requirements For The Department Of Transportation* for Standard Tree Protection Measures
Note: Inspection of worksite tree protection measures required by MC-DOT Arborist prior to construction activities
Note: ROW not to be utilized for staging area unless otherwise permitted by MC-DOT Arborist prior to construction activities

ADDRESS	SPECIES	LOCATION	DBH	RECOMMENDATIONS
3224 Sandburg Terrace	Silver Maple	1R-P	44	F, Air Excavation required. sidewalk to be located between concrete swale and road
3224 Sandburg Terrace	Silver Maple	2R-P	37	F, Air Excavation required. sidewalk to be located between concrete swale and road
3220 Sandburg Terrace	Mulberry	2R-P	13	F, Air Excavation required, elevate 8' over proposed s/w
Sidewalk to be located between concrete swale and road				
3216 Sandburg Terrace	Black Walnut	1R-P	20	F, Air Excavation required, elevate 8' over proposed s/w
Sidewalk to be located between concrete swale and road				
17132 Old Baltimore Rd				No trees on county right of way at this address
17314 Old Baltimore Rd	Willow Oak	1F-P	36	F, Air Excavation required
17136 Old Baltimore Rd				No trees on county right of way at this address
17112 Thorntondale Ct				No trees on county right of way at this address along Old Baltimore Rd
17108 Thorntondale Ct	Redbud	1R-P	18	F, elevate 8' over proposed s/w
17108 Thorntondale Ct	Redbud	2R-P	15	F, elevate 8' over proposed s/w
17104 Thorntondale Ct	Callery Pear	1R-P	25	F, note: minor trunk decay
	Callery Pear	2R-P	27	Removal Recommended ; tree in poor condition with extensive trunk decay.
Note: Allocation of funds into the <i>Street Tree Replacement Fund</i> is not required.				
1. Hand prune roots where noted above.				
2. Any roots 2" diameter or larger exposed by air excavation or by hand pruning activities, that require removal due to sidewalk construction, shall be inspected by ISA certified arborist with the Tree Maintenance Section, Montgomery County, prior to removal.				
3. An approved contractor certified in the State of Maryland for air excavation will be required to conduct all excavation where "Air Excavation required" is noted above.				
4. Arborist (Tree Maintenance Section, Division of Highway Services) shall be notified by Project Manager of root pruning and air excavation schedule prior to scheduled work.				
5. Root pruning shall be to the depth of excavation (no more than 6" depth)				
6. Excavation for proposed sidewalk shall be no more than 6"				

ADDRESS	SPECIES	LOCATION	DBH	RECOMMENDATIONS