

#### Welcome to Wheaton Revitalization News!

**Wheaton Revitalization News** is an email distribution list that will provide frequent updates to the surrounding community on the Wheaton Revitalization project. The purpose of this distribution list is to provide you with project updates and construction activities. For additional information on the Wheaton Revitalization Project please visit <a href="http://www.wheatonproject.com">http://www.wheatonproject.com</a>

Weekly Look Ahead – September 3 to September 7, 2019

#### GRANDVIEW AVENUE TO BE CLOSED ON SATURDAY SEPT 7th

Grandview Avenue will be closed on Saturday, **September 7<sup>th</sup> from 4am to 5pm** to stage a large mobile crane to hoist the cooling system and mechanical systems atop the building. This is a one-day closure and will not impact pedestrian traffic.

#### **Work along Triangle Lane**

The Contractor continues with construction of five (5) bio-filtration pits along the west side of Triangle Lane. Bio-filtration devices are concrete boxes measuring roughly 12-feet by 5-feet that contain a special soil mixture and bio-sensitive plantings that filter storm water discharged by the Office Building. When fully-planted, the bio-retention areas will also serve as an attractive array of plant material aesthetically enhancing the area. Concrete deliveries, planned during the early-morning hours, will be carefully monitored to avoid traffic disruptions. Triangle Lane will **NOT** be closed to traffic.

### **Project Status:**

The project remains on-schedule for a May 31, 2020 substantial completion and is currently 72-percent complete.

Interior work including: mechanical, electrical, ducts, sprinkler, plumbing, and interior wall framing underway through the 12<sup>th</sup> floor. The exterior sheathing installation continues through the 14<sup>th</sup> floor. Window installation continues through the 13<sup>th</sup> floor. The glass curtain wall is installed along the front of the building facing Reedie Drive. Storefront glass is installed along Triangle Lane where the new retail businesses will locate.

Building occupation and tenant move-in is scheduled during summer 2020.

# Garage

Electrical, mechanical, and sprinkler installation nearly complete.

Painting is underway. Construction of the garage is 85-percent complete.

### **Office Building**

### First Floor

Concrete complete.

Rough-in of mechanical, electrical, and piping underway.

Duct installation ongoing.

Sprinkler installation underway

Stairs erected.

Interior walls are being framed.

Storefront glass installed along Triangle Lane at the retail spaces.

Glass curtain wall Glass-front installed at Reedie Drive.

Curtain wall installed at the front of the building facing Reedie Drive.

### **Second Floor (Hearing Room)**

Concrete complete.

Rough-in of mechanical, electrical, and piping underway.

Duct installation ongoing.

Sprinkler installation underway

A mock-up of the 2<sup>nd</sup> floor bathroom continues to come-together but not yet complete.

Interior walls framing complete.

Wall close-ins underway way.

Stairs erected.

Glass front installed along Reedie Drive

Curtain wall framing installation underway.

#### **Third Floor**

Concrete complete.

Rough-in of mechanical, electrical, and piping underway.

Duct installation underway.

Interior wall framing complete.

Sprinkler installation underway

Exterior sheathing installation complete.

Waterproofing (blue skin) installation complete

Air barrier complete

Window installation complete

Stairs erected.

#### **Fourth Floor**

Concrete complete.

Rough-in of mechanical, electrical, and piping underway

Sprinkler installation underway

Wall framing complete

Sprinkler installation underway

Exterior sheathing installation complete.

Waterproofing (blue skin) installation complete

Air barrier complete Window installation complete Stairs erected.

#### Fifth Floor

Concrete complete.
Rough-in of Mechanical, electrical, and piping.
Sprinkler installation underway
Wall framing complete

Sprinkler installation underway
Exterior sheathing installation complete.
Waterproofing (blue skin) installation complete
Air barrier complete
Window installation complete

#### **Sixth Floor**

Concrete complete.
Rough-in of mechanical, electrical, and piping.
Wall framing complete
Sprinkler installation underway
Sprinkler installation underway
Exterior sheathing installation complete.
Waterproofing (blue skin) installation complete
Air barrier complete
Window installation complete

#### **Seventh Floor**

Concrete complete.
Interior wall framing underway
Exterior sheathing installation complete
Rough-in of mechanical, electrical, piping
Sprinkler installation underway
Exterior sheathing installation complete.
Waterproofing (blue skin) installation complete
Air barrier complete
Window installation complete

### **Eighth Floor**

Concrete complete
Core framing underway
Sprinkler installation underway
Mechanical, electrical, and duct installations started
Interior wall framing underway
Exterior sheathing installation complete.
Waterproofing (blue skin) installation complete
Air barrier complete
Window installation complete

### **Ninth Floor**

Concrete complete.
Wall framing underway
Duct installation underway
Rough-in mechanical, electrical, piping
Sprinkler installation underway
Sprinkler installation underway
Exterior sheathing installation complete.
Waterproofing (blue skin) installation complete
Air barrier complete

#### **Tenth Floor**

Window installation complete

Concrete complete.
Duct work underway
Main plumbing underway
Main electrical underway
Sprinkler installation underway
Exterior sheathing installation complete.
Waterproofing (blue skin) installation complete
Air barrier complete
Window installation complete

#### **Eleventh Floor**

Concrete complete.

Main electrical underway

Duct installation underway

Main plumbing underway

Sprinkler installation started

Exterior sheathing installation complete.

Waterproofing (blue skin) installation complete

Air barrier complete

### **Twelfth Floor**

Concrete complete.

Main plumbing underway
Installation of exterior sheathing underway
Sprinkler installation underway
Exterior sheathing installation underway
Waterproofing (blue skin) installation underway
Air barrier underway

#### **Thirteenth Floor**

Concrete complete. Installation of sheathing underway Main plumbing underway Electrical rough-in underway Piping rough-in underway Exterior sheathing installed Waterproofing and air barrier

# **Fourteenth Floor**

Concrete complete.

Main plumbing rough-in


Electrical rough-in

Framing for exterior sheathing underway

# Penthouse

Concrete complete

Piping and other mechanical system equipment delivered to Penthouse awaiting installation





Main Lobby Glass Installation Sept 2019



# **Town Plaza**

The Town Plaza will include an amphitheater, stage, lighting, art work, Wi-Fi, bio-retention areas, landscaping, and elevated walkways to Georgia Ave (to the south) and to the WAMTA tower connecting to the WMATA parking garage located on Viers Mill Road.

The contractor is forming and placing foundation elements for the stage, bio-retention areas, and the elevated walkways. This work will continue over the next several weeks.

Town Square Footer Construction August 19, 2019



### **Project Milestone Schedule**

Activity Completion Date

Demolition of RSC Bld. Complete Building tie-down anchors Complete **Geothermal Piping** Complete **Foundation Construction** Complete Complete Building Reaches Street Level **Utility Installation** Complete **Town Square** Spring 2020 **Complete Building top-out Building Close-in** October 2019 Interior build-out Spring 2020 **Substantial Completion** May 30, 2020 Summer 2020 Move-in (occupancy)

### **Upcoming and Ongoing Activities**

# ✓ Grandview Avenue to be closed on September 7, 2019, 4am to 5pm

- ✓ Bio-retention areas under construction along Triangle Lane
- ✓ Elevator equipment hoisted onto the rooftop
- ✓ Mechanical equipment to Penthouse
- ✓ Generators hoisted onto the rooftop
- ✓ Plumbing, electrical, and mechanical installations continues on floors through 12<sup>th</sup> floor
- ✓ Interior wall framing on floors complete through 6<sup>th</sup> floor and continuing through 9<sup>th</sup> floor
- ✓ Exterior sheathing installation complete through the 13<sup>th</sup> floor and climbing
- ✓ Application of blue-skin waterproofing complete through the 12<sup>th</sup> floor and climbing
- ✓ Application of Air Barrier through 13<sup>th</sup> Floor
- ✓ Offsite material fabrications underway
  - o Stone
  - o Misc metals
  - Windows
  - o Building skin
  - o Chillers HVAC
  - Interior lights
- ✓ Town Plaza (South of Reedie Drive)
  - Rough grading complete
  - o Installation of storm drain lines continue
  - o Drilling of micro-piles complete
  - o Placement of concrete foundations for elevated walkways underway
  - o Placement of concrete foundations for bio-retention areas underway
  - o Placement of concrete foundations for stage underway

# Follow Project Progress via the Project Camera

A camera has been installed to view construction on the site. The camera can be accessed by clicking the following link:

https://na01.safelinks.protection.outlook.com/?url=https%3A%2F%2Fapp.oxblue.com%2Fopen%2Fclark construction%2FWheatonPublic&data=01%7C01%7CKeith.Compton%40montgomerycountymd.gov%7C 830c4a63c9e34404c3ac08d501d8fad1%7C6e01b1f9b1e54073ac97778069a0ad64%7C1&sdata=nhBRXjh %2FEsi9abgWUtnqebo%2BWFQNa5eYTm4JQZIFlRg%3D&reserved=0